

ILLUSTRATION
SHOWS UNSANITARY
WATER MAIN
CONSTRUCTIONS
CONDITIONS
USING PRIOR ART
METHODS AND
EQUIPMENT.







FIG. 1



GUY WALTER

6419 3RD AVENUE

BRADENTON, FL 34208

941-748-2427

TRI VALVE FOR BACK FLOW PREVENTER ASSEMBLY

FIG. 1A






FIG. 2




TRI VALVE FOR BACK FLOW PREVENTER ASSEMBLY


GUY WALTER
6419 3RD AVENUE
BRADENTON, FL 34208
941-745-2427

FIG. 2




TRI VALVE





PRIOR ART






FIG. 6